



ನವ ಮಂಗಳೂರು ಬಂದರು ಪ್ರಾಧಿಕಾರ
ನವ ಮಂಗಳೂರು ಪತ್ತನ ಪ್ರಾಧಿಕರಣ
NEW MANGALORE PORT AUTHORITY
(Fully Solar Powered)

ಭಾರತ ಸರ್ಕಾರ (ಪತ್ತನ, ಪೊತ ಪರಿವಹನ ಔರ ಜಲಮಾರ್ಗ ಮಂತ್ರಾಲಯ)
Govt of India (Ministry of Ports, Shipping and Waterways)

ಪಣಂಬೂರು ಪಣಮ್ಬೂರು Panambur / ಮಂಗಳೂರು ಮಂಗಳೂರು Mangalore - 575010

75
Azadi Ka
Amrit Mahotsav



SAGARMALA
PORT-LED PROSPERITY

No. NMPA/DTM (N)/2024

08.07.2024

TRADE NOTICE

Sub: Bad Weather advisory for Oil Terminal Berths.

Ref:- 1) TN No.NMPA/DTM(N)/2024/OT Berths dtd. 01.06.2024

2) TN No.NMPA/DTM(N)/2024 dtd. 22.06.2024

3) Bad weather Advisory of Sr.DTM email dated 30.06.2024

In view of the ongoing Squally weather with Widespread Rain/Thunderstorm prevailing in this region & forecasted heavy weather in the coast of Karnataka, it is advised to take all necessary safety precautions to safeguard and prevent damage/loss to property and human lives. Some of the common safety precautions and checks to be undertaken by the Operators are given below:

1. Ensure that structures, equipments, sheets and other materials shall be secured firmly to avoid flying off during inclement weather.
2. Check all the electrical installations in the terminal/facility to prevent short circuits
3. Damaged /broken window panes and doors etc. should be repaired to prevent water getting into electrical rooms/ cabins/equipment rooms which may cause serious damage to the systems. Also prevent seepage of water into equipment rooms.
4. Necessary painting of various structures/installations and removal of debris, metal chips from underneath pipeline racks are to be taken up on immediate basis wherever required.
5. Necessary maintenance work of the installations may be carried out after taking necessary approval from Fire and safety division.
6. Loading arms and connected pipelines and valves may be checked. If corroded, the maintenance of the same may be done on immediate basis.
7. Check the metal stairs, railing etc in the terminals/facility and if corroded the same needs to be replaced/painted and maintained before monsoon.
8. All catch water drains and side drains must be clear of silt, vegetation and other obstruction to ensure free flow of water.
9. Working of all standby power supply.

In addition to the above, any other safety measures as deemed appropriate with regard to inclement weather preparedness may be undertaken by the terminals.


TRAFFIC MANAGER

Copy to

- All Oil Terminal Operators for strict compliance
- All HoDs/ DC, CISF for information
- Addl. Assistant Director, Inspectorate of Dock Safety, NMPA for information
- Sr.DTM/DTM/ATM Gr.1 (Comm.)/ATM Gr.1 (Opn.)/SO for necessary action
- Sr. Dy. Director, EDP for publishing in the NMPA website
- PS to Chairperson/PS to Dy. Chairperson for kind information

ದೂರವಾಣಿ / ದೂರಭಾಷ / Phone : 0824- 2407341, 2887399

आईएसओ 9001:2015, 14001:2015, 45001: 2018 एवं आईएसपीएस अनुपालनकर्ता पत्तन

An ISO 9001:2015, 14001:2015, 45001: 2018 & ISPS Compliant Port